CASE HISTORY (EI-32A Quarters – Timber Piling Repairs)



- Offshore living quarters supported by timber pilings.
- Timber pilings had severely deteriorated and the operator was forced to de-man the living quarters.
- MADCON provided a full structural repair to all pilings utilizing our proprietary repair techniques.
- Living quarters were placed back in service.

© MADCON Corporation 2016

This document is proprietary and confidential. No part of this document may be disclosed in any manner to a third party without the prior written consent of MADCON Corporation.

CASE HISTORY (EI-32A Quarters)



Severely Deteriorated Pile- Type I




Total Loss Of Section- Type II

© MADCON Corporation 2016

This document is proprietary and confidential. No part of this document may be disclosed in any manner to a third party without the prior written consent of MADCON Corporation.

CASE HISTORY (EI-32A Quarters)



Completed Structural Repairs

PH: 985.863.7773 **www.madcon.com** **info@madconcorp.com**

© MADCON Corporation 2016

This document is proprietary and confidential. No part of this document may be disclosed in any manner to a third party without the prior written consent of MADCON Corporation.